



- Machine Taps
- Maschinen-Gewindebohrer
- Machinetappen
- Tarauds machine
- Machos de máquina
- Macho de Máquina



E610



■ 3.1 3.2 3.3

• 1.1 1.2 1.3 1.4 1.5 3.4 6.2 6.3 6.4 7.2 7.3 7.4 8.2 8.3

M	P mm	l_1 mm	l_2 mm	d_2 \varnothing mm	\square a mm	l_3 mm	z		l_4 mm	e-Code
3	0,50	66	11	3,15	2,50	5	3	2.5	22	E610M3NO3
4	0,70	73	13	3,15	2,50	5	3	3.3		E610M4NO3
6	1,00	89	19	4,50	3,55	6	3	5		E610M6NO3
5	0,80	79	16	4,00	3,15	6	3	4.2		E610M5NO3
8	1,25	97	22	6,30	5,00	8	3	6.8		E610M8NO3
10	1,50	108	24	8,00	6,30	9	3	8.5		E610M10NO3
12	1,75	119	29	9,00	7,10	10	3	10.3		E610M12NO3
14	2,00	127	30	11,20	9,00	12	4	12		E610M14NO3
16	2,00	137	32	12,5	10,0	13	4	14		E610M16NO3