


- 粗切立铣刀
- Fraises d'ébauche
- Schruppfräser
- Fresa de Desbaste
- Fresas Gran Desbaste
- Roughing End Mill




## C400



- 1.2 1.3 6.2 6.3
- 1.1 1.4 2.1 3.1 3.2 3.3 3.4 4.1 4.2 5.1 5.2 6.1 7.2 7.3 8.1

d <sub>1</sub> Ø	d <sub>2</sub> Ø	l <sub>2</sub>	l <sub>1</sub>	z	e-Code	d <sub>1</sub> Ø	d <sub>2</sub> Ø	l <sub>2</sub>	l <sub>1</sub>	z	e-Code
6.00	6	13	57	4	C4006.0	20.00	20	38	104	4	C40020.0
7.00	10	16	66	4	C4007.0	22.00	20	38	104	4	C40022.0
8.00	10	19	69	4	C4008.0	24.00	25	45	121	4	C40024.0
9.00	10	19	69	4	C4009.0	25.00	25	45	121	5	C40025.0
10.00	10	22	72	4	C40010.0	26.00	25	45	121	5	C40026.0
11.00	12	22	79	4	C40011.0	28.00	25	45	121	5	C40028.0
12.00	12	26	83	4	C40012.0	30.00	25	45	121	5	C40030.0
13.00	12	26	83	4	C40013.0	32.00	32	53	133	6	C40032.0
14.00	12	26	83	4	C40014.0	36.00	32	53	133	6	C40036.0
15.00	12	26	83	4	C40015.0	40.00	40	63	155	6	C40040.0
16.00	16	32	92	4	C40016.0	50.00	50	75	177	6	C40050.0
18.00	16	32	92	4	C40018.0						



## C413



- 1.2 1.3 1.4 3.1 3.2 3.3 3.4 4.2 5.2 6.2 6.3
- 1.1 1.5 1.6 2.1 2.3 4.1 4.3 5.1 5.3 6.1 6.4 7.2 7.3 7.4 8.1

d <sub>1</sub> Ø	d <sub>2</sub> Ø	l <sub>2</sub>	l <sub>1</sub>	z	e-Code	d <sub>1</sub> Ø	d <sub>2</sub> Ø	l <sub>2</sub>	l <sub>1</sub>	z	e-Code
6.00	6	13	57	4	C4136.0	22.00	20	38	104	4	C41322.0
8.00	10	19	69	4	C4138.0	25.00	25	45	121	5	C41325.0
10.00	10	22	72	4	C41310.0	28.00	25	45	121	5	C41328.0
12.00	12	26	83	4	C41312.0	30.00	25	45	121	5	C41330.0
14.00	12	26	83	4	C41314.0	32.00	32	53	133	6	C41332.0
16.00	16	32	92	4	C41316.0						
18.00	16	32	92	4	C41318.0						
20.00	20	38	104	4	C41320.0						