

- 机用铰刀 极不等距
- Alésoir machine Pas différentiel
- Maschinenreibahle Extrem ungleiche Teilung
- Alargador Máquina com Espaçamento Extremamente Desigual
- Escariador de máquina Espacio extremadamente irregular
- Machine Reamer Extremely Unequal Spacing



## B411



- 1.5 1.6 3.1 3.2 3.3 3.4 4.1 4.2 4.3 5.1 5.2 5.3 6.1 6.2 6.3 6.4 7.1 7.2 7.3 7.4
- 8.1 8.2
- 1.1 1.2 1.3 1.4

d <sub>1</sub> Ø	l <sub>1</sub>	l <sub>2</sub>	l <sub>3</sub>	z	MK	e-Code
5.0	133	23	67.5	6	1	B4115.0 <sup>1)</sup>
6.0	138	26	72.5	6	1	B4116.0 <sup>1)</sup>
7.0	150	31	84.5	6	1	B4117.0 <sup>1)</sup>
8.0	156	33	90.5	6	1	B4118.0 <sup>1)</sup>
9.0	162	36	96.5	6	1	B4119.0 <sup>1)</sup>
10.0	168	38	102.5	6	1	B41110.0 <sup>1)</sup>
12.0	182	44	116.5	6	1	B41112.0 <sup>1)</sup>
14.0	189	47	123.5	8	1	B41114.0 <sup>1)</sup>
15.0	204	50	124	8	2	B41115.0 <sup>1)</sup>
16.0	210	52	130	8	2	B41116.0 <sup>1)</sup>

d <sub>1</sub> Ø	l <sub>1</sub>	l <sub>2</sub>	l <sub>3</sub>	z	MK	e-Code
17.0	214	54	134	6	2	B41117.0 <sup>2)</sup>
18.0	219	56	139	6	2	B41118.0 <sup>2)</sup>
19.0	223	58	143	6	2	B41119.0 <sup>2)</sup>
20.0	228	60	148	6	2	B41120.0 <sup>2)</sup>
22.0	237	64	157	6	2	B41122.0 <sup>2)</sup>
24.0	268	68	169	8	3	B41124.0 <sup>2)</sup>
25.0	268	68	169	8	3	B41125.0 <sup>2)</sup>
26.0	273	70	174	8	3	B41126.0 <sup>2)</sup>
30.0	281	73	182	8	3	B41130.0 <sup>2)</sup>

<sup>1)</sup> 整体硬质合金 / Carbure monobloc / VHM / Metal Duro / Monobloc de Metal Duro / Solid Carbide

<sup>2)</sup> 硬质合金刀头 / Tête carbure / VHM-Kopf / Cabeça de Metal Duro / Cabeza de Metal Duro / Carbide Head