



- Machine Taps
- Maschinen-Gewindebohrer
- Machinetappen
- Tarauds machine
- Machos de máquina
- Macho de Máquina



E712



- 1.3 1.4
- 1.1 1.2 1.5 3.1 3.2 3.3 3.4 6.2 7.3 7.4 8.1

NPTF	TPI	d ₁ nom mm	l ₁ mm	l ₂ mm	d ₂ Ø mm	∅ a mm	l ₃ mm		l ₄ mm	z	e-Code
1/16	27	7,94	65	17	8,1	6,0	8	6.2	17	4	E7121/16
1/8	27	10,29	70	19	11,1	8,3	10	8.4	19	4	E7121/8
1/4	18	13,72	75	27	14,3	10,7	11	10.9	27	4	E7121/4
3/8	18	17,15	80	27	17,8	13,5	13	14.25	27	4	E7123/8
1/2	14	21,34	100	35	17,5	13,1	16	17.75		4	E7121/2
3/4	14	26,67	105	35	23,0	17,2	17	23		5	E7123/4
1	11.5	33,40	115	43	28,6	21,4	21	29		5	E7121
1.1/4	11.5	42,16	125	43	33,4	24,9	23	37.75		5	E7121.1/4